

GM CUSTOMER CARE AND AFTERSALES
DCS3078
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 24, 2013

Subject: 13360 – Service Update – Low Rear Differential Fluid Level –
CORRECTED VIN LIST – ADDITIONAL VINS ADDED

Models: 2014 Chevrolet Corvette

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

All involved vehicles must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in the bulletin has been performed on the vehicles.

Additional vehicles have been added to this Service Update. Please disregard all previous lists sent to you and use the corrected VIN list attached to this message. For your convenience, a copy of the bulletin is also attached to this message.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES