



Field Service Bulletin

Release: August 30, 2013

Subject: Lower Rivet Holding

As an owner of a Wheeled Coach/Road Rescue vehicle, your satisfaction with our products is very important to us. The purpose of this courtesy notification is to recommend that you inspect the lower rivet holding the cross member to the frame just behind the rear axle. For your reference, we have attached pictures showing the correct placements of the lower rivet holding. Below are the vehicle(s):

Model Year	Model Type	VIN	Customer Name

If you notice any displacement or dislodgement of the lower rivet, please contact our Customer Service Department at 800-932-7077, ext 295 or 302. Our customer service office is open Monday – Friday from 8 a.m. to 5 p.m. eastern standard time.

Sincerely,

Fred Birchfield
Quality Assurance Manager
fred.birchfield@wheeledcoach.com



Showing the location of the Lower Rivet Holding



Correct placement of Lower Rivet Holding