



Das Auto.

# Warranty Information

**Policies and Procedures Bulletin**

**Number: VWP-13-13**

**Subject: Secondary Air Pressure Sensor Limited Warranty Extension (US Dealers)**

**Date: June 25, 2013**

This document modifies the Volkswagen Warranty Policies and Procedures Manual.

## Secondary Air Pressure Sensor Limited Warranty Extension

Volkswagen has extended the Emissions Control Systems Warranty for secondary air pressure sensor replacement under specific conditions to 10 years or 120,000 miles, whichever occurs first, from the vehicle's original in-service date, for the following 2.5 L engine vehicles:

- ▶ 2009 MY Rabbit (A5) with Engine Codes CBUA and CBTA
- ▶ 2009 MY Jetta Wagon (A5) with Engine Codes CBUA and CBTA
- ▶ 2009 MY Jetta (A5) with Engine Codes CBUA and CBTA
- ▶ 2010 MY Jetta (A5) with Engine Code CBUA
- ▶ 2010 – 2012 MY Jetta SportWagen (A6) with Engine Code CBUA
- ▶ 2011 – 2012 MY Jetta (A6) with Engine Code CBUA
- ▶ 2012 MY Passat with Engine Code CBUA
- ▶ 2012 MY Beetle with Engine Code CBUA
- ▶ 2010 – 2012 MY Golf (A6) with Engine Code CBUA

Certain states have voluntarily adopted California-mandated emissions warranties only for vehicles equipped to meet California's Partial Zero Emissions Vehicle (PZEV) emissions requirements. These vehicles can be identified by inspecting the Vehicle Emission Control Information Label located under the hood. Because of this, the owner of a vehicle equipped to meet California's PZEV emissions requirements living in one of these states may have warranty rights that exceed the extended warranty offering described in this bulletin. Owners should refer to the warranty information that came with their vehicle for additional details as to whether or not this applies to their vehicle.

The vehicle's original in-service date is defined as the date the vehicle was delivered to either the original purchaser or the original lessee; or if the vehicle was first placed in service as a "demonstrator" or "company" car, on the date such vehicle was first placed in service.

This warranty extension is fully transferable to subsequent owners.

## What is the Problem

Volkswagen has determined that under specific conditions, certain deficiencies affecting the secondary air pressure sensor could make the secondary air pressure sensor susceptible to degraded performance. If this happens, the Malfunction Indicator Lamp (MIL) on the instrument cluster may illuminate due to the presence of specific fault codes caused by a faulty secondary air pressure sensor. (The MIL is part of the on-board diagnostic system. Please refer to the owner's manual for additional information about the MIL.) In some locales, an illuminated Malfunction Indicator Lamp could cause the vehicle to fail an IM emissions



Das Auto.

# Warranty Information

---

inspection, and the vehicle registration application could be denied. Volkswagen has not identified any vehicle drivability concerns related to this issue.

Please be aware that other conditions (unrelated to the issue described in this bulletin) may cause the MIL in the vehicle to illuminate. Customers should be prepared to cover all diagnosis and repair costs for these other, unrelated conditions.

## What does this Warranty Extension Cover

This warranty extension covers only the diagnosis and replacement of the secondary air pressure sensor.

## What is Not Covered Under This Warranty Extension

This warranty extension will *not* cover:

- ▶ Any damage or malfunctions caused by installation of non-EPA or non-CARB certified parts, or parts that alter the performance of the engine, engine controls, or exhaust system, such as the installation of engine management components ("chipped" or "tuned" ECMs) not approved by Volkswagen.
- ▶ Other conditions *unrelated* to the secondary air pressure sensor that may cause the MIL to illuminate. These conditions may require repairs that are needed for proper diagnosis of the underlying condition. Any repairs that are (1) necessary for proper diagnosis of these other conditions or (2) required to bring the vehicle's emission system up to factory specifications are not covered by this warranty extension.
- ▶ Damage or malfunctions caused by outside influence, such as damage due to an accident, or vehicle misuse or neglect, as well as repairs that are (1) necessary for proper diagnosis of these other conditions or (2) required to bring the vehicle up to factory specifications are not covered by this warranty extension.

## Repair Procedure

Refer to Technical Bulletin Instance Number 2028415 for the applicable repair procedure.

## Vehicle Eligibility

To determine if a vehicle is eligible for the Secondary Air Pressure Sensor Limited Warranty Extension, check the VIN in ElsaWeb > Vehicle-Specific Notes > Vehicle Data. If the warranty extension is applicable to the vehicle, the "Enhanced Coverage" section of the "Vehicle Data" screen in ElsaWeb will be populated with the warranty extension parameters.

## SAGA Warranty Claim Type and Service Number

Dealers must use the following claim type and service number when submitting warranty claims for the Secondary Air Pressure Sensor Limited Warranty Extension.

- ▶ Claim Type: 110
- ▶ Service Number: 2666

## Questions

For any questions regarding this warranty extension, please contact the Warranty Helpline at 1-866-306-8447 or [warranty.helpline@vw.com](mailto:warranty.helpline@vw.com).

# Warranty Quick Reference Guide Updates

Periodically updated pages of the Warranty Quick Reference Guide will be reprinted and shipped to Dealers for inclusion into the guide. In the interim, in order to keep the guide up-to-date, please print this update and insert into the applicable section(s) of the guide.

Volkswagen Limited Extension Warranties	Country	Model Year	Model	Engine	Years (Whichever Occurs First)	Miles
Positive crankcase ventilation (PCV) valve limited warranty extension	USA	2006 - 2008	Jetta	2.0L TFSI/BPY	10	120,000 mi
			GTI	2.0L TFSI/BPY		
			Eos	2.0L TFSI/BPY		
			Passat Sedan / Wagon	2.0L TFSI/BPY		
Front wheel bearings limited warranty extension	USA	2009 - 2010	Routan	All	5	90,000 mi
Engine exhaust flap limited warranty extension	USA	2009 - 2012	2.0L TDI® Clean Diesel engine vehicles	CBEA CJAA CKRA	10	120,000 mi
Secondary air pressure sensor limited warranty extension	USA	2009	Rabbit (A5)	CBUA, CBTA	10	120,000 mi
			Jetta Wagon (A5)	CBUA, CBTA		
		2010	Jetta (A5)	CBUA, CBTA		
			Jetta (A5)	CBUA		
		2010 - 2012	Jetta SportWagen (A6)	CBUA		
2011 - 2012	Jetta (A6)	CBUA				

Warranty Extensions Chart continued next page

# Warranty Quick Reference Guide Updates

Periodically updated pages of the Warranty Quick Reference Guide will be reprinted and shipped to Dealers for inclusion into the guide. In the interim, in order to keep the guide up-to-date, please print this update and insert into the applicable section(s) of the guide.

Volkswagen Limited Extension Warranties	Country	Model Year	Model	Engine	Years (Whichever Occurs First)	Miles
Secondary air pressure sensor limited warranty extension	USA	2012	Passat	CBUA		
		2012	Beetle	CBUA	10	120,000 mi
		2010 - 2012	Golf (A6)	CBUA		