



Service Bulletin

PRELIMINARY INFORMATION

Subject: Pre-Delivery Inspection (PDI) - Wiper Blade Protector Covers Removal

Models: 2013 Chevrolet Spark

Condition/Concern

Below is a specific area that needs to be emphasized when performing a pre-delivery inspection (PDI) on the vehicle listed. This item is either unique to this vehicle or have significant impact on initial customer satisfaction.



Technicians may notice a light white plastic triangle the length of the blade, which touches the windshield as shown in the illustration above.



During PDI, technicians should remove the light white plastic triangle protective cover, as shown in the illustration above, off the wiper blades and discard.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION