



Countries:	CANADA, UNITED STATES	Document ID:	IK0800424
Availability:	ISIS, FleetISIS, Body Builder	Revision:	1
Major System:	ELECTRICAL SYSTEM	Created:	5/6/2013
Current Language:	English	Last Modified:	5/6/2013
Other Languages:	NONE	Author:	Will (Mark) Wiley
Viewed:	128		

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 3	Not Helpful 0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------


Title: Wingman DTC Report

Applies To: Bendix Wingman Systems

DESCRIPTION

Follow this procedure when attaching Wingman DTC Reports to Tech Service Case Files.


Creat by using ACom V6.5 or higher.




In ACB STATUS click DTCs.



In the DTC Window click report.



Fill in Company, Technician and VIN, press OK.



Select Save, Click OK. Save to your Desktop, then attach to case file.

Failure#	Description	Frequency counter
1	Internal radar sensor error (1)	0
2	Internal radar sensor error (2)	0

ReportMode

Report Mode

Print

Print Preview

E-mail to Bendix

Save

OK Cancel

DTC Description Internal radar sensor error

Tests Possible causes:
Some error conditions may occur at extreme high or low temperatures. These trouble codes must be diagnosed with the ambient temperature above 32°F (0°C) and below 100°F (38°C)
Perform the following:
• Clear the Wingman Advanced trouble codes using the procedure in

Hide Details

Feedback Information

Viewed: 127
 Helpful: 3
 Not Helpful: 0

No Feedback Found