



Countries: CANADA, UNITED STATES, MEXICO
Availability: ISIS, FleetISIS, Body Builder
Major System: ELECTRICAL SYSTEM
Current Language: English
Other Languages: [Français](#), [Español](#),
Viewed: 2165
Document ID: IK0800207
Revision: 3
Created: 1/21/2010
Last Modified: 11/13/2013
Author: Joe Christopher

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 647	Not Helpful 396
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	---------------------------	-------------------------------

Title: High output alternator replacement on CF500 and CF600 CityStar® models.

Applies To: All CityStar® models (CF500 and CF 600)

DESCRIPTION

A high output alternator is now available for the CF500 and CF600 CityStar® models. Attached to this document are Supplier instructions that outline the replacement of original alternator with a high output Leece Neville AVI160T Alternator rated at 230 Amps .
 The higher output alternator requires a mounting kit, belt and an electrical cable upgrade kit as listed below.

PARTS INFORMATION

Part Number	Source	Description	Qty.
LNAVI160T2002-3	PDC	230 Amp Alternator includes Mounting Kit K069105628S	1
2603824C91	PDC	Kit, cable upgrade.	1
1893842C1	PDC	Belt, w/ AC	1
1893843C1	PDC	Belt, w/o AC	1

SERVICE PROCEDURE

Utilize the parts and part numbers listed in this document.
 Follow the Technical Service Bulletin (TSB-1142) from Leece Neville below for installation instructions.

Link to: [Leece Neville TSB-1142 \(PDF\)](#)

NOTE:	<p>The information supplied herein has been furnished by the manufacturer and/or the supplier for use with its product. Navistar, Inc. reprints this information based on representations made to the company. While users are urged to carefully follow the instructions accompanying the product, Navistar cannot accept any responsibility for user errors, or mishaps resulting from such errors, or from any misuse of the product.</p>
--------------	--

Hide Details

Feedback Information

Viewed: 2164
Helpful: 647
Not Helpful: 396

No Feedback Found