



SI M64 01 13
Heating and Air Conditioning

April 2013
Technical Service

SUBJECT

Red or Blue Cap Missing from Temperature Control Wheel

MODEL

R55

R56

R57

Produced to July 31, 2010 with option 0534 (automatic air conditioning)

SITUATION

The customer states the red or blue cap is missing from the temperature control wheel of the heat and air conditioning control panel.

PROCEDURE



1. The red and blue caps can now be replaced separately. Note: Replacement of the complete heat and air conditioning panel is no longer permitted for this complaint. Replace the missing cap(s).

2. The red and blue caps come as a set, and only the missing part needs to be replaced. Press the appropriate color cap into the opening (red towards the top and

blue towards the bottom).



PARTS INFORMATION

Part Number	Description	Quantity
64 11 9 318 950	Temperature control caps (blue and red)	1

WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty.

Defect Code:	64 11 64 13 00	
Labor Operation:	Labor Allowance:	Description:
64 99 000	3 FRU	Work time to complete the repair procedure (Main work)
or		
64 99 000	1 FRU	Work time to complete the repair procedure (Plus work – vehicle is already in the workshop)

[Copyright ©2013 BMW of North America, Inc.]