

Measure no.

US 53826418-01

Subject

R1200R has no fuel level or engine temperature display, despite having an on-board computer

Status date (mm/dd/yy)

3/14/13

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/14/13

Created by

Bernhard Kistler

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K27/11

Engine**Body****Production period (from/to)**

(mm/dd/yy)

3/3/13 /

Comment on production period

from factory integration level

K024-13-02-500

Feedback (all cases relating to**measure up to) (mm/dd/yy)**

Complaint

R1200R has no fuel level or engine temperature display in the instrument cluster, despite having an on-board computer

Cause

From 03/04/2013, with factory integration level K024-13-02-500, the film sensor (and therefore the fuel level and engine temperature display in the instrument cluster) is discontinued for option X539 on-board computer.

Measure

No measure. The missing fuel level and engine temperature display in the instrument cluster corresponds to the release and the Owner's Manual.

Complaint**Fault location**

62/11 Instrument cluster

Fault type

Software error

Fault place

Cause

#

Fault location**Fault type****Fault place**



1

62/11 Instrument cluster

Software error

Repair Task

Special Clearance

Area

No

Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System

State

Version

© 2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.