

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Delivery Stop: F01, F02, F15 Parking Brake Switch Update 1
Date: Wednesday, November 13, 2013 1:54:30 PM

Publish Date: November 13, 2013
From: Technical Service
Expiration Date: November 27, 2013

DCSnet Message 
Important

Subject: **Delivery Stop: F01, F02, F15 Parking Brake Switch Update 1**

To: General Managers, Sales Managers, Service Managers, Service and Parts Directors, Service Advisors and Shop Foremen,

A Delivery Stop has been issued on certain 2014 model year F01, F02 and F15 vehicles produced from June 2013 to mid October 2013. A fault in the parking brake (EMF) switch could cause a Check Control message (Parking Brake Failure) to display. However, all braking functions, including the parking brake and switch continue to operate properly in this case.

Affected vehicles in center inventory must not be delivered until the parking brake switch has been replaced.

Parking brake switches for the F15 must be ordered VIN-specific. **Update: vehicles held at a VDC (port facility) will have the switch replaced before release to a center. Therefore do not order parts for vehicles held at a VDC.** Refer to Service Information bulletin B61 20 13 for the part number and complete instructions.

Parts for the F01 and F02 are not available at this time. An availability update will be provided by November 20 (1 week).

Affected vehicles can be identified via the Key Reader, DCS Inquiry or ISPA with the description:

Defect Code 0061880300, Delivery Stop EMF Switch B61 20 13.

Sincerely,

Technical Service

Attachments: No Attachments No Attachments

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel