



Countries: Document ID: IK1200893  
 Availability: Revision: 0  
 Major System: ENGINES Created: 3/8/2013  
 Current Language: English Last Modified: 3/8/2013  
 Other Languages: NONE Author: David Smith  
 Viewed: 81

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark  <a href="#">View My Bookmarks</a>	Add to Favorites 	Print 	Provide Feedback 	Helpful  1	Not Helpful  0
---------------	------------------------	---	----------------------	-----------	----------------------	------------------	----------------------

**Title: 2010 MaxxFORCE 11/13 Oil Filter Cap and Bypass Valve Assembly**

**Applies To: Prostar, LoneStar, WorkStar, TranStar, 2010 MaxxFORCE 11/13**

**DESCRIPTION**

Warranty returned oil filters have been sent back along with the Oil Filter Cap Bypass Valve. The valve allows oil to pass through the engine if the filter becomes restricted. Please verify that at every oil change that the Oil Filter Cap has an intact Bypass Valve. If the Oil Filter Cap is missing the Bypass Valve please replace the Oil Filter Cap assembly with the part number 3007511C91. The kit will include : Oil Filter Cap with Bypass Valve, and Oil Filter Cap Seal.

**NOTE: THE BYPASS VALVE SHOULD NOT BE REMOVED FOR ANY REASON**

**PARTS INFORMATION**

Part #	Description	Qty.
3007511C91	Kit, Oil Filter Cover	1

For the Bypass Valve location refer to the image below:



Picture Below is an Oil Filter Cap with a Bypass Valve (on the left), and without the ByPass Valve (on the right).



 Hide Details

Feedback Information

Viewed: 80  
Helpful: 1  
Not Helpful: 0

No Feedback Found

Copyright © 2013 Navistar, Inc.