



# TECH TALK

## Index - 4th Quarter 2012

### 2012 TECH TALK INDEX (Volumes 186 – 192)

Model	Year(s)	Subject	Tech Talk Issue
<b><u>GENERAL</u></b>			
All Models	2009–12	Remote Engine Start Transmitter Will Not Unlock Doors	Vol.186, Jan/Feb, 2012
All Models	2012	TIN–12–00–001: Vehicle Receiving Inspection: “MiEV Remote Location”	Vol.187, Mar/Apr, 2012
All Models (CVT)	2008–12	J1 CVT Fluid Superseded to J4	Vol.187, Mar/Apr, 2012
All Models	All	Testing of Remote Transmitters	Vol.187, Mar/Apr, 2012
All Models	All	Hot Weather Seasonal Diagnosis	Vol.188, May/June, 2012
All Models	All	Techline Videos on MDL	Vol.188, May/June, 2012
All Models	All	Trailer Towing Limits	Vol.188, May/June, 2012
All Models	All	Manual Transmission Fluid Superseded	Vol.188, May/June, 2012
All Models	All	Increased Tire Inflation Pressure for Vehicle Shipment	Vol.188, May/June, 2012
All Models	2004–12	Air Conditioning Maintenance and Repair	Vol.188, May/June, 2012
All Models	All	New TSB Search Capability on MDL	Vol.189, July/Aug, 2012
All Models	All	Adjusting Torque Values When Using a Crow’s Foot	Vol.190, Sept/Oct, 2012
All Models	All	Vehicle Receiving Inspection – Road Salt Contamination	Vol.190, Sept/Oct, 2012
All Models (w/SRS)	All	TIN–12–52B–001: NHTSA Press Release on Counterfeit Airbags	Vol.190, Sept/Oct, 2012
All Models	All	Adjusting Torque Values When Using a Crow’s Foot	Vol.191, Nov, 2012
All Models	All	Vehicle Receiving Inspection – Road Salt Contamination	Vol.191, Nov, 2012
All Models	w/SRS	TIN–12–52B–001: NHTSA Press Release on Counterfeit Airbags	Vol.191, Nov, 2012
All Models	2008–13	Instructional Videos for Operating Vehicle Features	Vol.192, Dec, 2012
All Models	All	Using LEDs in Standard Stop Light Circuits	Vol.192, Dec, 2012
All Models	All	No Audio Response When “Speech” Button is Pressed	Vol.192, Dec, 2012
All Models	All	Radio Security Code Online Retrieval Available to Customers	Vol.192, Dec, 2012
<b><u>ECLIPSE</u></b>			
Eclipse	2006–12	Instrument Panel Deformation	Vol.186, Jan/Feb, 2012
Eclipse	2006–12	Noisy Exhaust Heat Shields	Vol.187, Mar/Apr, 2012
Eclipse	2010–12	DTCs B1702 & B1731 in PCM Memory	Vol.189, July/Aug, 2012
Eclipse	2000–05	DTC P0335 and/or P0340 During Wide Open Throttle	Vol.192, Dec, 2012
<b><u>ECLIPSE SPYDER</u></b>			
Eclipse Spyder	2007–12	Convertible Top Hydraulic O–Rings Available as Service Parts	Vol.186, Jan/Feb, 2012
Eclipse Spyder	2007–12	Instrument Panel Deformation	Vol.186, Jan/Feb, 2012
Eclipse Spyder	2007–12	Noisy Exhaust Heat Shields	Vol.187, Mar/Apr, 2012
Eclipse Spyder	2010–12	DTCs B1702 & B1731 in PCM Memory	Vol.189, July/Aug, 2012
<b><u>ENDEAVOR</u></b>			
Endeavor	2004–06	TPMS Sensor Registration	Vol.186, Jan/Feb, 2012
Endeavor	2004–11	Roof Rack Side Rail End Cover R & I	Vol.186, Jan/Feb, 2012
Endeavor	2004–12	Instrument Panel Deformation	Vol.186, Jan/Feb, 2012
Endeavor	2004–12	Front and Rear Door Water Leak	Vol.187, Jan/Feb, 2012
Endeavor	2010–11	DTCs B1702 & B1731 in PCM Memory	Vol.189, July/Aug, 2012

<b>Model(s)</b>	<b>Year(s)</b>	<b>Subject</b>	<b>Tech Talk Issue</b>
<b><u>ENDEAVOR (cont'd)</u></b>			
Endeavor	2011	Intermittent Speaker "Pop"	Vol.189, July/Aug. 2012
Endeavor	2007-11	Navigation System (Navi) Inop.	Vol.189, July/Aug. 2012
<b><u>GALANT</u></b>			
Galant	2004-06	TPMS Sensor Registration	Vol.186, Jan/Feb, 2012
Galant	2004-12	Instrument Panel Deformation	Vol.186, Jan/Feb, 2012
Galant	2004-12	Noisy Exhaust Heat Shields	Vol.187, Mar/Apr, 2012
Galant	2004-12	Front and Rear Door Water Leak	Vol.187, Jan/Feb, 2012
Galant	2009-12	DTCs B1702 & B1731 in PCM Memory	Vol.189, July/Aug, 2012
Galant	2009-12	Appearance of Headliner Around Sunroof	Vol.189, July/Aug. 2012
Galant	2011-12	Intermittent Speaker "Pop"	Vol.189, July/Aug. 2012
Galant	2012	Audio Control Knob Functions Reversed	Vol.189, July/Aug.2012
Galant	2011-12	Audio Control Knob Functions Reversed (REV)	Vol.191, Sept/Oct, 2012
Galant	1999-03	DTC P0335 and/or P0340 During Wide Open Throttle	Vol.192, Dec, 2012
<b><u>I-MiEV</u></b>			
i-MiEV	2012	Supporting the CCID During Regular Charging	Vol.186, Jan/Feb, 2012
i-MiEV	2012	Discharged 12V Starter Battery	Vol.186, Jan/Feb, 2012
i-MiEV	2012	No Start/Ready Mode After Charging Traction Battery	Vol.186, Jan./Feb, 2012
i-MiEV	2012	Navigation Inop at PDI	Vol.187, Mar/Apr, 2012
i-MiEV	2012	Battery Compensation Retention During Long Repairs	Vol.187, Mar/Apr, 2012
i-MiEV	2012	Mid-year Production Changes	Vol.188, May/June, 2012
i-MiEV	2012	Odometer and Cruising Range Display Installation and SRS (REVISED)	Vol.188, May/June, 2012
i-MiEV	2012	TIN-012-52A-001REV - Seat Cover (Including Leather) Installation and SRS (Revised)	Vol.189, July/Aug, 2012
i-MiEV	2012	ATIN-12-54-001: Customer Letter - Clipper Creek EVSE Charger	Vol.192, Dec. 2012
<b><u>LANCER</u></b>			
Lancer	2010-11	TSB-11-13-008REV: P0016 or P0017- Crankshaft/Camshaft Position	Vol.186, Jan/Feb, 2012
Lancer	2009-12	New Timing Chain for Turbocharged Engines	Vol.187, Mar/Apr, 2012
Lancer	2008-12	Electrical Interference from Aftermarket Accessories	Vol.188, May/June, 2012
Lancer	2011-12	Real Time Traffic (RTT) Feature Inop	Vol.188, May/June, 2012
Lancer	2008-13	TS-SST Axle Seal Oil Leak	Vol.190, Sept/Oct, 2012
Lancer	2011-12	Resetting the Bluetooth Security Lockout Passcode	Vol.190, Sept/Oct, 2012
Lancer	2009-13	TS-SST Axle Seal Oil Leak	Vol.191, Nov, 2012
Lancer	2011-12	Resetting the Bluetooth Security Lockout Passcode - Corrected	Vol.191, Nov, 2012
Lancer	2012-13	TPMS Sensor Registration Procedure	Vol.192, Dec, 2012
Lancer	2008-13	Navigation Screen Displays New York City/ Clock Will Not Set	Vol.192, Dec, 2012
Lancer	2011-13	Remote Engine Start Registration Won't Complete	Vol.192, Dec, 2012
<b><u>LANCER EVOLUTION</u></b>			
Lancer Evolution	2010-11	TSB-11-13-008REV: P0016 or P0017- Crankshaft/Camshaft Position	Vol.186, Jan/Feb, 2012
Lancer Evolution	2008-12	New Timing Chain for Turbocharged Engines	Vol.187, Mar/Apr, 2012
Lancer Evolution	2008-12	Electrical Interference from Aftermarket Accessories	Vol.188, May/June, 2012
Lancer Evolution	2011-12	Real Time Traffic (RTT) Feature Inop	Vol.188, May/June, 2012
Lancer Evolution	2008-13	TS-SST Axle Seal Oil Leak	Vol.190, Sept/Oct, 2012
Lancer Evolution	2011-12	Resetting the Bluetooth Security Lockout Passcode	Vol.190, Sept/Oct, 2012
Lancer Evolution	2008-13	TS-SST Axle Seal Oil Leak	Vol.191, Nov, 2012

<b>Model(s)</b>	<b>Year(s)</b>	<b>Subject</b>	<b>Tech Talk Issue</b>
<b><u>LANCER EVOLUTION (cont'd)</u></b>			
Lancer Evolution	2011-12	Resetting the Bluetooth Security Lockout Passcode – Corrected	Vol.191, Nov, 2012
Lancer Evolution	2012-13	TPMS Sensor Registration Procedure	Vol.192, Dec, 2012
Lancer Evolution	2008-13	Navigation Screen Displays New York City/ Clock Will Not Set	Vol.192, Dec, 2012
<b><u>LANCER SPORTBACK</u></b>			
Lancer Sportback	2010-11	TSB-11-13-008REV: P0016 or P0017- Crankshaft/Camshaft Position	Vol.186, Jan/Feb, 2012
Lancer Sportback	2009-12	New Timing Chain for Turbocharged Engines	Vol.187, Mar/Apr, 2012
Lancer Sportback	2008-12	Electrical Interference from Aftermarket Accessories	Vol.188, May/June, 2012
Lancer Sportback	2011-12	Real Time Traffic (RTT) Feature Inop	Vol.188, May/June, 2012
Lancer Sportback	2009-13	TS-SST Axle Seal Oil Leak	Vol.190, Sept/Oct, 2012
Lancer Sportback	2011-12	Resetting the Bluetooth Security Lockout Passcode	Vol.190, Sept/Oct, 2012
Lancer Sportback	2009-13	TS-SST Axle Seal Oil Leak	Vol.191, Nov, 2012
Lancer Sportback	2011-12	Resetting the Bluetooth Security Lockout Passcode – Corrected	Vol.191, Nov, 2012
Lancer Sportback	2012-13	TPMS Sensor Registration Procedure	Vol.192, Dec, 2012
Lancer Sportback	2009-13	Navigation Screen Displays New York City/ Clock Will Not Set	Vol.192, Dec, 2012
Lancer Sportback	2010-13	Remote Engine Start Registration Won't Complete	Vol.192, Dec, 2012
<b><u>OUTLANDER</u></b>			
Outlander	2010-11	TSB-11-13-008REV: P0016 or P0017- Crankshaft/Camshaft Position	Vol.186, Jan/Feb, 2012
Outlander	2011	No Response From Handsfree Module (HFM)	Vol.186, Jan/Feb, 2012
Outlander	2008-12	Electrical Interference from Aftermarket Accessories	Vol.188, May/June, 2012
Outlander	2011-12	Real Time Traffic (RTT) Feature Inop	Vol.188, May/June, 2012
Outlander	2010-12	Resetting the Bluetooth Security Lockout Passcode	Vol.190, Sept/Oct, 2012
Outlander	2010-12	Resetting the Bluetooth Security Lockout Passcode – Corrected	Vol.191, Nov, 2012
Outlander	2012-13	TPMS Sensor Registration Procedure	Vol.192, Dec, 2012
Outlander	2007-13	Navigation Screen Displays New York City/ Clock Will Not Set	Vol.192, Dec, 2012
Outlander	2010-13	Remote Engine Start Registration Won't Complete	Vol.192, Dec, 2012
<b><u>OUTLANDER SPORT/RVR</u></b>			
Outlander Spt/RVR	2010-11	TSB-11-13-008REV: P0016 or P0017- Crankshaft/Camshaft Position	Vol.186, Jan/Feb, 2012
Outlander Spt/RVR	2012	ATIN-12-SR-001: Turn Signal Cancellation & Inspection (U.S. Dealers Only)	Vol.186, Jan/Feb, 2012
Outlander Spt/RVR	2011-12	No Crank/No Start	Vol.186, Jan/Feb, 2012
Outlander Spt/RVR	2011-12	Replacing the Rear Dome Lamp Bulb	Vol.186, Jan/Feb, 2012
Outlander Spt/RVR	2012	RKE Integrated Key Repair Kit	Vol.187, Mar/Apr, 2012
Outlander Spt/RVR	2008-12	Electrical Interference from Aftermarket Accessories	Vol.188, May/June, 2012
Outlander Spt/RVR	2011-12	Real Time Traffic (RTT) Feature Inop	Vol.188, May/June, 2012
Outlander Spt/RVR	2011-12	No Start with "One Touch Start System" (OSS)	Vol.189, July/Aug, 2012
Outlander Spt/RVR	2013	Vibrating Noises from Under the Vehicle From 2500-3000 RPM	Vol.190, Sept/Oct, 2012
Outlander Spt/RVR	2013	Front Suspension Noise/Knock over Bumps	Vol.190, Sept/Oct, 2012
Outlander Spt/RVR	2013	Stop Light Switch Adjustment	Vol.190, Sept/Oct, 2012
Outlander Spt/RVR	2013	TPMS Sensor Registration	Vol.190, Sept/Oct, 2012
Outlander Spt/RVR	2011-13	FAST Key Registration & Security ID Registration Download for Canada Dealers	Vol.190, Sept/Oct, 2012
Outlander Spt/RVR	2013	A-Pillar Trim Loose	Vol.190, Sept/Oct, 2012
Outlander Spt/RVR	2011-12	Resetting the Bluetooth Security Lockout	Vol.190, Sept/Oct, 2012

<b>Model(s)</b>	<b>Year(s)</b>	<b>Subject</b> Passcode	<b>Tech Talk Issue</b>
<b><u>OUTLANDER SPORT/RVR (cont'd)</u></b>			
Outlander Spt/RVR	2013	Vibrating/Buzz Noise from Under the Vehicle from 2500–3000 RPM	Vol.191, Nov, 2012
Outlander Spt/RVR	2013	Front Suspension Noise/Knock Over Bumps	Vol.191, Nov, 2012
Outlander Spt/RVR	2013	Stop Light Switch Adjustment	Vol.191, Nov, 2012
Outlander Spt/RVR	2013	Outlander TPMS Sensor Registration	Vol.191, Nov, 2012
Outlander Spt/RVR	2011–13	Fast Key Registration & Security ID Registration Download for Canada Dealers	Vol.191, Nov, 2012
Outlander Spt/RVR	2013	A–Pillar Trim Loose	Vol.191, Nov, 2013
Outlander Spt/RVR	2011–12	Resetting the Bluetooth Security Lockout Passcode – Corrected	Vol.191, Nov, 2012
Outlander Spt/RVR	2013	TIN–12–42A–001: Outlander Sport TPMS Sensors – Temporary Production	Vol.192, Dec, 2012
Outlander Spt/RVR	2013	Buzz or Rattle Noise from Rear of Vehicle When Accelerating	Vol.192, Dec, 2012
Outlander Spt/RVR	2013	Squeak from Front Door Window	Vol.192, Dec, 2012
Outlander Spt/RVR	2011–13	TPMS Sensor Registration Procedure	Vol.192, Dec, 2012
Outlander Spt/RVR	2013	Loose “ASC OFF” Button	Vol.192, Dec, 2012
Outlander Spt/RVR	2013	Mirror Switch Investigation	Vol.192, Dec, 2012
Outlander Spt/RVR	2013	Fog Lamp Bezel Installation	Vol.192, Dec, 2012
Outlander Spt/RVR	2011–13	Navigation Screen Displays New York City/Clock Will Not Set	Vol.192, Dec, 2012
Outlander Spt/RVR	2013	“Random” Front Parking Sensor Alert	Vol.192, Dec, 2012
Outlander Spt/RVR	2011–13	Remote Engine Start Registration Won’t Complete	Vol.192, Dec, 2012