

Reference	SSM64157
Models	Range Rover (All New) / L405
Title	Spare Wheel Lift Assist Tool
Category	Accessories
Last modified	26-Mar-2013 00:00:00
Symptom	General Accessories
Content	<p>Issue: Reports received that the Spare Wheel Lift Assist Tool has not been supplied with the vehicle.</p> <p>Cause: The Spare Wheel Lift Assist Tool is only provided as standard for vehicles that are ordered with a 21" or 22" full size spare wheel only.</p> <p>Action: Check the spare wheel type and size before ordering a Spare Wheel Lift Assist Tool. If the vehicle is supplied with a 19" or 20" full size alloy spare wheel or a space saver wheel, the tool is not provided as standard and should not be claimed as warranty.</p> <p>Note: If the Spare Wheel Lift Assist Tool is found to be missing from a vehicle that is supplied with a 21" or 22" full size spare wheel <u>only</u> upon delivery, then a claim should be submitted using DDW against the 'MVCS-Mis-builds' program code.</p> <p>Note: Information regarding the Spare Wheel Lift Assist Tool is quoted in the PDI manual.</p>