


L405 Radiator Date code.pptx

L405 Radiator Leak.JPG

Reference	SSM66477
Models	Range Rover (All New) / L405
Title	L405 Radiator Leak
Category	Engine
Last modified	21-Jun-2013 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p>Issue: Loss of coolant, low level coolant warning displayed in the instrument cluster.</p> <p>Cause: Supplier quality issue - Radiator is found to be leaking from the inlet (top) tank left hand end clench (see attached picture for reference)</p> <p>Action: Replace radiator, part number LR034553. From the production dates of parts sent to Service (Neovia) the only affected radiators in service stock will have a date code of 12th Jan 2013 on the label (see attached example). If the radiator ordered from parts has a date code label other than 12th Jan 2013 it is ok to use. This SSM will be replaced with a Technical Bulletin at a later date.</p> <p>NOTE – Service stock was recalled and checked by the supplier, however if stock has been held at a Dealer it is recommended to check the date code prior to fitment.</p>



L25951 0P0A870AH43433ACD 12/01/13

P5

CALSONIC KANSEI UK

CPLA 8005 AB



Coolant leak from radiator upper tank joints.

