

T5 & Freelander Carpet mat fixings SSM (L359) 1a.JPG

Reference SSM62897

LR4 / L319

Models LR2 / L359

Range Rover Evoque / L538

Range Rover Sport / L320

Title Freelander & T5 Carpet mat fixings

Category Accessories

Last modified 05-Feb-2013 00:00:00

Symptom General Accessories

Issue:

Front carpet clip location may be incorrect

Cause:

Content Poor clip position

Action:

If it is seen that the front carpet mat does not fit correctly follow the attached instruction

Mats Retention Clips

