

9002523

03/27/2013

MY11-13

RT

GPOP - Issue Review System

Part Number: 05154214A\$

Part Description: Hub & Bearing Assy - Front

Issue Description: Before replacing this part for a noise issue, please review and follow the updated "Hub & Bearing Noise Diagnostic Procedure" found in Star News #75, and in Service Manual. See DealerCONNECT>TechCONNECT>Service INFO>Front Susp>Front/Hub and Bearing>Diagnosis and Testing>Diagnosis and Testing - Hub and Bearing - Noise.

~ _____ ~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.