

TECHNICAL BULLETIN
LTB00526NAS1
12 APR 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-00

Discolored Quarter Glass / Waist Seals

AFFECTED VEHICLE RANGE:

Range Rover Sport (LS)	Model Year:	2005-2013
	VIN:	900129 Onwards

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The quarter glass / waist seals may become discolored.

Cause: This may be caused by the seals becoming contaminated from external sources.

Action: In the event of a customer concern of the above, refer to the Repair Procedure outlined below.

PARTS:

 **NOTE: KATS Transit Coating Remover to be locally sourced; one bottle sufficient for 10 vehicles.**

 **NOTE: An allowance \$3.05 has been provided to cover the cost of the cleaner and should be claimed using code 'ZZZ001'.**

Source KATS Transit Coating Remover 8077 (Jaguar part number C2C38875) from your local Jaguar Dealer.	Quantity: 1
---	-------------

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

 **NOTE: An allowance \$3.05 has been provided to cover the cost of the cleaner and should be claimed using code 'ZZZ001'.**

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**


 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME	CONDITION	CAUSAL PART
-------------	-----	------	-----------	-------------

		(HOURS)	CODE	
Cleaning of Quarter Glass Seals / Waist Seals	05.10.10	0.10	81	LR044524

 **NOTE: Normal Warranty policies and procedures apply.**


SERVICE INSTRUCTION:

-  **NOTE: Vehicle surface temp should be 16-27C (60-80F). Avoid temperature in excess of 63C (145F).**

 **NOTE: Recommendation dilution is 1:8 KATS Transit Coating Remover: fresh water.**

Using a suitable small spray bottle, mix the KATS Transit Coating Remover with fresh water (1 part remover:8 parts fresh water); shake bottle before application.

- Rinse affected area down with fresh water to remove grit and dust.



- Spray affected parts with dilution and then gently wipe with soft cotton cloth to remove staining.
- Rinse off with fresh water and dry with a **clean** soft cotton cloth.
- Make sure that the quarter glass / waist seal is aesthetically pleasing on the eye.
- If required, repeat procedure to the other quarter glass / waist seals as necessary.