Special Service Message



NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 64637	- Battery Warni	ng Message Displayed	
Models :	X250 - XF		
	X351 - XJ		
Engineer Name :	Payne Gary		
Last Modified :	16-04-2013 07:43:36		
Category :	Electrical		
Symptom :	203000 Basic Electrical		
Content :	: <u>Issue</u>		
		that prior to starting the engine or with management or Low Battery message r both.	
		the Power Budget available to cust s. (Note: The available Budget is re	
	Model	FCDIM/HLDF display	IPK display
	XJ 10-12 MY	"Low Battery - Please switch engine on or entertainment syster will shut down in 3 mins."	"Low Battery- m Please start engine"
	XJ 13MY onwards	"Energy management - System w shut down in 3 minutes"	
	XF 12MY onwards (Exc 2.2D from 14my onward	cept "Energy management - System w ds) shut down in 3 minutes"	^{/ill} None
	Cause 2: Battery state of charge has been reduced to 50%		
	Model	FCDIM/HDLF Display	IPK Display
	XJ 10 - 12 MY	"Low Battery - Please switch engine on or Entertainment system will shutdown in 3mins."	Please start engine"
	XJ 13MY onwards	"Energy management - System will shutdown in 3 minutes"	"Low Battery- Please start engine"
	XF 12MY onwards (Except 2.2D from 14MY onwards)	"Energy management - System will shutdown in 3 minutes"	"Low Battery- Please start engine"
	engine not running prior	omer, if any vehicle features had been to the message appearance. If so ad ction of the vehicle to protect the cust	lvise the customer

experiencing a discharged battery.

	 If an issue is suspected check the following before commencing with in depth diagnostics:- Carry out a battery test using a Midtronics tester, follow the recommended actions as per the "Battery Care requirements" document located in Topix Section 414:00. Check the BMS and Battery cables to ensure that no loose connections exist. 	
Jaguar Land Rover Limited 2000 - 2013 (Rel. 2.5.1.0)		