



# Tech Tips

TT 46-09-04

Date: October 23, 2009

2006-2010 Passat, 2009-2013 CC, Tiguan – Synchronization of the EPB Switch and EPB Module

April 12, 2013: Update to Models and Model Years.

If fault code 03200 or 16352 is present in the Electromechanical Parking Brake (EPB) module, it may be due to the switch and module not being synchronized.

To synchronize the EPB switch and EPB control module:

- Insert the ignition key to the run position
- Press and hold the EPB switch
- Cycle the ignition off and then back to the run position
- Let off of the EPB button.