

**On-car analysis list from March 21st, 2013
please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Golf R	12	All	All	Transmission	Transmission Concerns (including clutch assembly, bevel box and Haldex)
	Golf, Jetta, Jetta SportWagen, Passat	09-13	2.0 TDI	All	Cylinder Contribution Faults: P0263, P0266, P0269 and/or P0272	MIL on
	Golf, Jetta, Jetta SportWagen, Beetle, Passat	11-13	2.0 TDI	All	Any DPF replacement	MIL on
	Golf, Jetta, Jetta SportWagen, Beetle, Beetle Convertible, Passat	12-13	2.5L CBUA	All	Fault code P050A stored in Engine Control Module with no other DTCs stored	MIL on
	Golf, Jetta, Jetta SportWagen, Beetle, Passat, CC	13	All	All	Fuel gauge reads high/low/incorrect with no associated faults	Fuel gauge not reading correctly
	Golf, Jetta, Jetta SportWagen	09-13	2.0 TDI	All	Ice/Water in intercooler after intercooler kit installation	Hard to start, Will not start
	GTI, Jetta, Beetle, Tiguan, CC, EOS	12-13	2.0TFSI - CCTA & CBFA	All	P0087 - Low fuel pressure (untouched vehicles in the NJ, PA, NY, MI, OH, IL, IN, southern CA and Las Vegas areas only)	MIL on
	Touareg	13	3.0 TDI	All	Particulate Matter Sensor Fault P24AF	MIL on
Electrical	Jetta, Beetle, Jetta SportWagen	2013	All	All	Key Remote Functions Inoperative or No Start with Key Remote at PDI	Key Remote Functions Inoperative or No Start with Key Remote at PDI
	Passat	2013	all	all	No Start with Key Remote at PDI (Kessy)	Vehicle will not start with one or both keys at PDI
	All Except Routan	2012 - 2013	All	All	Door Wiring Harness	Malfunction of: Power Mirror(s), Power Window(s), Power Door Lock(s), KESSY Function(s).
	Passat	2013	all	all	Key will not turn in ignition	Key will not turn in ignition
GFF	Touareg	2004-2006	All	All	Immobilizer (provide pass/fail immobilizer ignition key adaptation diagnostic log strictly using and completing the GFF test plan with the latest GFF software version)	Key Inoperative / Adaption / Replacement
Body	Jetta SW	2012-2013	All	All	Door Handle	When the vehicle is unlocked the exterior door handle takes multiple pulls to open door (Only vehicles produced after VIN 3VWPP7AJ2CM694585)