



# Service Bulletin

File in Section: -

Bulletin No.: PIT4551F

Date: June, 2013

## PRELIMINARY INFORMATION

**Subject:** Back Up Alarm Inoperative And Needs To Be Connected During PDI

**Models:** 2008-2013 Chevrolet Silverado  
2014 Chevrolet Silverado 2500 / 3500  
2008-2013 GMC Sierra  
2014 GMC Sierra 2500 / 3500  
Equipped with Back Up Alarm (RPO 8S3)

This PI was superseded to update model list. Please discard PIT4551E.


The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

During the PDI it may be noticed that the backup alarm is inoperative. On trucks equipped with the Back Up Alarm option RPO 8S3, the alarm will be intentionally left disconnected from the assembly plant.

### Recommendation/Instructions

The alarm is located on the right rear of the frame, and the chassis harness alarm connector is located on the left rear of the frame. Route the harness up and over the spare tire hoist tube and connect to the backup alarm.



1. Back Up Alarm/Connector
2. Spare Tire Hoist Tube

2044179

## **Warranty Information**

This procedure is part of the vehicle's PDI process and should not be charged to warranty.

### **ADDITIONAL SI KEYWORDS:**

reverse shift

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.