



Service Bulletin

File in Section: -

Bulletin No.: PIP4781E

Date: December, 2013

PRELIMINARY INFORMATION

Subject: HYBRID (BAS) TAC SGCM Part Restriction

Models: 2008-2010 Chevrolet Malibu Hybrid
2007-2010 Saturn Vue Hybrid
2007-2009 Saturn Aura Hybrid
All with RPO code HP7. With any of the DTCs listed in the Keyword Section below.

This PI was superseded to remove the part restriction. Please discard PIP4781D.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Effective 12/2/2013, the SGCM (Starter Generator Control Module) will be removed from the GM Technical Assistance Center (TAC) Parts Restriction.

Recommendation/Instructions

Although it is no longer necessary to order the SGCM through GM TAC, TAC will still be available for support as needed during normal business hours.

ADDITIONAL SI KEYWORDS:

P0A37 P0A38 P0A39 P0A4B P0AF8 P0AFB P1AB1 P1AB3 P1AB4 P1AB5 P1AB6 P1AB7 P1AB8 P0B09 P2796
P0A50 P0A8E P1A8D P1A8E P1AA7 P0A87 P0A88 P0A89 P1A63 P1A69 P1A70 P1A6A P1A6B P1A6D P1A6E
P1A90 P1A91 P1A92 P1A93 P1A94 P1A95 P1A96 P1A97 P1A98 P0A1E P0A06 P0A07 P0A4C P0A7C P0A92
P0AF7 P1A56 P1A62 P1A7B P1A7C P1A7D P1A9B P1A9C P1A9D P1AA0 P1AA1 P1A9E P1AA2 P1AAE P1AAF
PIP4781 PIP4781A PIP4781B PIP4781C PIP4781D PIP4781E 24248545

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.