

SB-10052248-9733

Repair Notice

413-7

Section

HVAC

Description

Model 587 Air Conditioner Charge

Release Date

5/20/2013

Introduction

Peterbilt Motors has decided that certain model 587 vehicles built between November 5, 2012 and April 1, 2013 have too much refrigerant in the air conditioning system. The over charge situation will cause the compressor and fan clutch to cycle excessively and the HVAC system to underperform.

Expiration Date: May 29, 2014

Resolution

Peterbilt has issued this field repair notice to remove the refrigerant and recharge the system with the correct amount.

Warranty

The SIR system will indicate chassis involved in this field repair with the designator "413-7" in the campaign field.

If the vehicle is affected and is shown to have an open campaign, please complete the work and file quick claim 413-7.

Parts

There are no parts required to complete this repair.

Labor

The field repair will reimburse a total of 1.5 hrs to recover and recharge refrigerant to the a/c system.

Procedure

Recover the system refrigerant and recharge the HVAC system according to the label located on the front wall of the cab.

For reference:

Refrigerant charge amount	
587 day cab	3.2 lb
587 sleeper cab	3.6 lb

Attachments

[Customer letter](#)

[Dealer chassis list](#)

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2013 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).