

SB-10052840-3243

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR AUGUST 2013**

44129 2014 Escape - Driver's Seat Module Calibration, DTC P1188

Some 2014 Escape vehicles equipped with power seats may exhibit DTC P1188 stored in the Driver's Seat Module (DSM). When a new DSM has been installed, the driver seat hard stops must be calibrated using a scan tool. DTC P1188 maybe set when a the calibration is not completed. This is not a false DTC, however, DTC P1188 and corresponding pin point test are currently not available in the 2014 Escape Workshop Manual; updates will be completed by the end of fourth quarter. Also, the IDS menu selection for this calibration procedure is currently not available, but is due to be updated in IDS 86.51.