

SB-10053363-9399

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2013**

32225 2013 Focus ST - Bang Noise Heard And/Or Bump Felt From Front Of Vehicle During Quick
1-2 And/Or 2-3 Shifts Under Moderate To Aggressive Acceleration

Some 2013 Focus ST vehicles may exhibit a bang noise heard and/or bump felt from front of vehicle during quick 1-2 and/or 2-3 shifts under moderate to aggressive acceleration. Engineering is currently investigating this condition through the quicker service fix (QSF) process. Until new parts are available, do not attempt repair. Monitor OASIS for updates.