



File in Section: -

Bulletin No.: PI1088

Date: October, 2013

Service Bulletin

PRELIMINARY INFORMATION

Subject: Information on Proper Auxiliary Power Connections


Models: 2011-2014 Chevrolet Caprice PPV
Equipped with Auxiliary Battery RPO K4S or K5S

Condition/Concern

Improper electrical connections using the power studs on the isolation relay rather than the provided power studs. Any added power circuit in the trunk electrical center should not utilize the studs on the isolation relay.

Recommendation/Instructions

The Caprice PPV equipped with the auxiliary battery utilizes an isolation relay to protect the auxiliary battery from being discharged during engine starting. To eliminate the possibility of improper power tapping, refer to the image below to identify the location of the proper power taps on vehicles equipped with the auxiliary battery, which is located in the trunk of the vehicle directly behind the RH wheel.



3634969

Legend

- (1) Auxiliary Power Taps (shown with cover open)
- (2) Isolation Relay - DO NOT use as power taps