

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR NOVEMBER 2013**

44286

2014 Escape - Various Electrical Issues Due To Poor Connection at Ground G107

Some 2014 Escape vehicles built on or before 9/22/13 may exhibit various electrical issues - erratic wiper operation, headlamps flicker or inop, turn signals cut in and out, and/or hood ajar warning on. Front park lamps, fog lamps, active grille shutter and cooling fan operation may also be affected. This may be due to a poor connection at ground G107 in the lower left front fender apron. Clean the ground connection and re-secure.