



Mercedes-Benz
The best or nothing.

star bulletin



Date: January 9, 2013
Order No.: T-B-72.20/115a
Supersedes: T-B-72.20/115; January 3, 2013
Group: 72

Revision a: Revised for Model Number clarity in title.

**SUBJECT: MY-All, Model 166.OXX with Code 890 Easy-Pack Liftgate
Liftgate Control Drive Unit**

There is a new drive unit (part A 166 890 11 30) with modified performance characteristics. Once the old drive unit (part A 166 890 04 30) is out-of-stock, only the new drive unit will be available. When installing the new drive unit in vehicles, the codes must be entered in the VeDoc online vehicle data card: code 802 for MY2012, code 803 for MY2013, or code 122 for future model years.

Finally, the liftgate control unit (N121/1) must be coded using the Xentry DAS with software calibration number (SCN).

Parts Information

Qty.	Part Name	Part Number
1	"Old" drive spindle	A 166 890 04 30
1	"New" drive spindle	A 166 890 11 30

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

© 2013 Mercedes-Benz USA, LLC.
Mercedes-Benz Canada, Inc.
Dealer Workshop Services
www.MBUSA.com
www.startekinfo.com

All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in U.S.A.
1-800-FOR-MERCedes