



**Internal notification for: G_0000158519 12262 - Service Update - Seat
Memory Control Module Reprogram - Revised**
gm_gmssg_q01

02/07/2013 03:25 PM

2 attachments



12262 SRX Insert.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 02/07/2013

Ref. number: Service / Field Action / G_0000158519

Subject: 12262 - Service Update - Seat Memory Control Module Reprogram - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2905
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 7, 2013

Subject: 12262 - Service Update Bulletin
Seat Memory Control Module Reprogram
Revised Owner Manual Supplement for SRX Vehicles Only

Models: 2013 Cadillac ATS, SRX, XTS Equipped with Seat Memory Feature

To: All Cadillac Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The wheel nut torque on page 3 of the Owner Manual Supplement for the SRX has been revised to 150 N•m (110 lb ft).

If you have vehicles in dealer inventory that have been repaired and a copy of the older version of the supplement was placed in the glove box or Owner Manual, please discard it and replace it with this new revised supplement.

If copies of the supplement were made for convenience, please discard them and replace them with the new supplement.

The revised supplement for the SRX can be found in the GlobalConnect Library, message number D_0000072220. A copy has also been included with this message.

The Owner Manual Supplement for the ATS and XTS have not changed.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES