
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Wednesday, November 27, 2013 5:21 AM
To:
Subject: Internal notification for: G_0000179791 13376 - Service Update - Front Bumper Fascia Air Deflector Replacement
Attachments: 13376 bulletin.pdf; 13376 Inventory VINs.xlsx

Date: 11/27/2013

Ref. number: Service / Field Action / G_0000179791

Subject: **13376 - Service Update - Front Bumper Fascia Air Deflector Replacement**

GM CUSTOMER CARE AND AFTERSALES
DCS3102
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 27, 2013

Subject: 13376 – Service Update Bulletin
Front Bumper Fascia Air Deflector Replacement

Models: 2013 Chevrolet Malibu Equipped with Active Grille Shutters (VRI) and Located in Alabama, Arkansas, Arizona, Florida, Georgia, Louisiana, Mississippi, New Mexico, Oklahoma, South Carolina, Texas

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, Used Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Service Update Bulletin 13376 today. The total number of U.S. vehicles involved is approximately 2,800. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The “Investigate Vehicle History” (IVH) screen will be updated November 27, 2013. A list of involved vehicles in dealer inventory is attached to this message.

Service Update Bulletin (SUB) Information Link

The SUB Information Link in GlobalConnect will be updated in the near future.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES
