



**Internal notification for: G\_0000157036 12319A - Noncompliance Recall - Possible Missing Secondary Hood Latch - Revised gm\_gmssg\_q01**

01/23/2013 05:36 AM

2 attachments



12319A bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/23/2013

Ref. number: Service / Field Action / G\_0000157036

Subject: 12319A - Noncompliance Recall - Possible Missing Secondary Hood Latch - Revised

**GM CUSTOMER CARE AND AFTERSALES  
DCS2883  
URGENT - DISTRIBUTE IMMEDIATELY**

Date: January 23, 2013

Subject: 12319A - Noncompliance Recall  
Possible Missing Secondary Hood Latch  
Customer Letter Added

Models: 2010-2012 Chevrolet Colorado and GMC Canyon

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, Used Vehicle Sales Manager, and Warranty Administrator

Bulletin 12319A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 12319.

Customer Letter Mailing

The customer letter mailing will begin on January 28, 2013.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12319A bulletin.pdf Acrobat PDF (396.8KB)  
12319A bulletin

Phone:

t: