



Internal notification for: G_0000163304 13098A - Safety Recall - Steering Wheel Fastener Inspection - Revised
gm_gmssg_q01

04/04/2013 11:07 AM

2 attachments



13098A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 04/04/2013 Ref. number: Service / Field Action / G_0000163304
Subject: 13098A - Safety Recall - Steering Wheel Fastener Inspection - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2938
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 4, 2013
Subject: 13098A - Safety Recall
Steering Wheel Fastener Inspection
Revised Vehicle Model Description
Models: 2013 Buick Encore
To: All Buick Dealers
Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

Bulletin 13098A has been revised to include vehicles equipped with heated and non-heated steering wheels. Please discard all copies of bulletin 13098.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13098A bulletin.pdf Acrobat PDF (649.2KB)
13098A bulletin

Contact name: E-Mail:
Department: Phone:
Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, roles: Service Advisor, Service Manager, Warranty Administrator
Archives 05/04/2013 Expires: 04/04/2014