



## TECH TIP: Rear Parking Lamps Inop

NUMBER: TT020

MODEL: 2011 Optima

DATE: 11/15/2013

**Symptom:** Rear parking lamps inoperative.

**Repair:** Perform Service Action SA080 for BCM logic improvement to correct this concern.

Note: Tech Tips are not a substitute for proper diagnosis.