

Unable to Turn OFF Seat Heater

Service Category Vehicle Interior

Section Seat

Market USA

Toyota Supports
 ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2013	Avalon, Avalon HV	

Introduction

Some 2013 model year Avalon XLE and Avalon HV XLE vehicles may exhibit front seat heaters remaining ON in the lowest setting even when the seat heater switch is OFF. Replace the seat heater switch (Refreshing Seat Switch) to address this condition.

Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	ENGINE	PLANT	PRODUCTION CHANGE EFFECTIVE VIN
Avalon	2GR-FE	TMMK	4T1BK1EB#DU023518
Avalon HV	2AR-FXE		4T1BD1EB#DU005940

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
EL1307	R & R Seat Heater Switch	0.3	84752-07010	82	71

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Parts Information

PART NUMBER	PART NAME	QTY
84752-07010	Switch, Refreshing Seat	1

Unable to Turn OFF Seat Heater

Repair Procedure

1. Confirm the condition exists as described in the Introduction.
2. Remove and replace the seat heater switch (Refreshing Seat Switch).

Refer to the Technical Information System (TIS), applicable model and model year Repair Manual:

- 2013 Avalon / Avalon HV:
Vehicle Interior – Seat – “Seat: Seat Heater Switch: Removal”
 - 2013 Avalon / Avalon HV:
Vehicle Interior – Seat – “Seat: Seat Heater Switch: Installation”
3. Verify the seat heater operates normally.