



Service Bulletin

File in Section: -

Bulletin No.: PIT4551E

Date: February, 2013

PRELIMINARY INFORMATION

Subject: Back Up Alarm Inoperative And Needs To Be Connected During PDI

Models: 2008-2013 Chevrolet Silverado
2008-2013 GMC Sierra
Equipped with Back Up Alarm (RPO 8S3)

This PI was superseded to update model years and warranty information. Please discard PIT4551D.


The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

During the PDI it may be noticed that the backup alarm is inoperative. On trucks equipped with the Back Up Alarm (RPO 8S3), the alarm will be intentionally left disconnected from the assembly plant.

Recommendation/Instructions

The alarm is located on the right rear of the frame, and the chassis harness alarm connector is located on the left rear of the frame. Route the harness up and over the spare tire hoist tube and connect to the backup alarm.



1. Back Up Alarm/Connector
2. Spare Tire Hoist Tube

Warranty Information

This procedure is part of the vehicle's PDI process and should not be charged to warranty.

ADDITIONAL SI KEYWORDS:

reverse shift

2044179

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.