



# Service Bulletin

File in Section: -

Bulletin No.: PIP4560R

Date: October, 2013

## PRELIMINARY INFORMATION

**Subject:** Allison LCT1000 PQC TCM Part Restriction

**Models:** 2012-2014 Chevrolet Silverado  
2012-2014 GMC Sierra  
Equipped With Allison LCT1000 Transmission RPO MW7

This PI was superseded to remove TCM P/N 24256861 from restriction. Please discard PIP4560Q.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

As part of our ongoing quality improvement efforts, the Allison TCM Part Number 24256861 has been removed from the PQC parts restriction effective 10/17/2013.

Your cooperation with this program is greatly appreciated.

### Recommendation/Instructions

Perform published service information diagnostics and if diagnostics leads to TCM replacement the part can be ordered through your parts department.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.