



# Service Bulletin

File in Section: -

Bulletin No.: PIC5873

Date: June, 2013

## PRELIMINARY INFORMATION

**Subject:** Heated Seats Inoperative

**Models:** 2013 Chevrolet Malibu (Build before 12/01/2012)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern


A customer may comment that either heated seat is inoperative when the switch is depressed, may indicate that one side may not come on unless the other side is on, or the switch must be depressed a second time before heated seat will come on.

### Recommendation/Instructions

With vehicle running, depress the Config button of the radio controls, scroll down, and select "Vehicle Settings" on display. Next, scroll down and select "Return to Factory Settings?". Once selected, you will see "Return to Factory Settings?" on the display with Yes and No boxes below. Select Yes, The screen will now display "Factory Settings Set". Confirm correct operation of the heated seats.



3460861



3460859

## Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
*2880048	Perform Factory Reset for Heated Seats	0.2 hr
* This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.