



Service Bulletin

File in Section: -

Bulletin No.: PIC5872

Date: June, 2013

PRELIMINARY INFORMATION

Subject: Normal Characteristic - XLR Folding Top Tech2 Rear Tonneau Status Value Blank Or Missing

Models: 2004 - 2009 Cadillac XLR

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

During diagnosis of the folding top and/or trunk operation, the technician may find that the Tech2 value for the Rear Tonneau Status is blank.

Recommendation/Instructions

Important: Do NOT replace parts for this condition. Always reference published diagnostics and the latest revision of TSB 03-08-67-008 when diagnosing any trunk or folding top concerns.

This blank value is caused by a Tech2 software malfunction and has nothing to do with the function or operation of the vehicle. The data is NOT needed to diagnose folding top or trunk concerns, it is only a calculated value determined from other Tech2 values displayed within the same Inputs data list. The use of existing data will allow proper diagnosis.

To work around this blank data value, use the following Folding Top Module, Inputs data parameters:

Rear Tonneau Position Sensor

Rear Tonneau Open Reference Position

Rear Tonneau Close Reference Position

These three parameters are displayed in Counts from 0 - 255. Below are three examples of how to determine what the Rear Tonneau Status is. The specific count values below are examples only and in no way indicate a specific value that should be seen on any given vehicle.

Note: Open (Retracted) and Closed (Extended) values will vary from vehicle to vehicle. The following values are provided for demonstration / example purposes only.

In this example, the Status will be Mid whenever the Sensor counts are between, or in the middle of, the Open and Close Reference values.

Rear Tonneau Status Mid.

Rear Tonneau Position Sensor 150 Counts

Rear Tonneau Open Reference Position 188 Counts

Rear Tonneau Close Reference Position 112 Counts

In this example, the Status will be Retracted whenever the Sensor Counts are equal to or greater than the Open Reference value.

Rear Tonneau Status Retracted

Rear Tonneau Position Sensor 191 Counts

Rear Tonneau Open Reference Position 188 Counts

Rear Tonneau Close Reference Position 112 Counts

In this example, the Status will be Extended whenever the Sensor Counts are equal to or less than the Close Reference value.

Rear Tonneau Status Extended

Rear Tonneau Position Sensor 109 Counts

Rear Tonneau Open Reference Position 188 Counts

Rear Tonneau Close Reference Position 112 Counts

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.