

Damper assy markings (2).pdf

Reference	SSM67957
Models	F-TYPE / X152
Title	Clarification of Correct Rear Damper Module Build Condition
Category	Chassis
Last modified	05-Sep-2013 00:00:00
Symptom	304000 Suspension System
Content	<p><u>Issue:</u> This SSM is issued to clarify the correct build condition on rear Damper Modules, for correct Spring packer / Spacer fitment.</p> <p><u>Action:</u> If the bottom Paint mark on the Spring is White, then there should be a Spring packer/Spacer fitted. Paint mark Spring packer/Spacer V6 PassiveYellow / White Yes V6 Active Yellow/ White Yes V8 Active Pink / WhiteYes</p> <p>If the bottom Paint mark on the Spring is Orange, then there should not be a Spring packer / Spacer fitted. Paint mark Spring packer / Spacer V8 ActiveBlue / Orange No V6 PassiveBlue / Orange No V6 Active Blue / Orange No</p> <p>Refer to photo for example of paint marking. This SSM should be read in conjunction with Technical Bulletin JTB00396v2 - Suspension Knock/Creak From Rear Of Vehicle.</p>



EX5B18