



Service Bulletin

File in Section: -

Bulletin No.: PIC5831

Date: March, 2013

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Convertible Roof Rivet Replacement

Models: 2011 - 2014 Chevrolet Camaro Convertible

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern


The Electronic Parts Catalog (EPC) may show multiple different rivet sizes and this could create confusion regarding which rivet is needed for which location.

Recommendation/Instructions

Using the illustration will aid in the dealer obtaining the correct rivet for the repair being performed.

Callout #1 represents Part Number 11546538

Callout #2 represents Part Number 11546537



3346640

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.