



# Service Bulletin

File in Section: 08 - Body and Accessories

Bulletin No.: 13-08-43-001

Date: October, 2013

## INFORMATION

**Subject:** Information on Windshield Wiper Blade Identification

**Models:** 2014 Chevrolet Silverado 1500  
2014 GMC Sierra 1500

### Windshield Wiper Blade Design and Identification

Although both front windshield wiper blades appear to be the identical, the wiper blades are unique right and left components. They are individually designed to prevent lift in extreme high wind conditions and are not interchangeable.



3620607

The windshield wiper blades are marked DS for driver side and PS for passenger side on the mounting clip. When servicing or replacing the windshield wiper blades, ensure the correct blade position is observed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION