

TECHNICAL BULLETIN
LTB00612NAS1
19 NOV 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-10

'Creak' Noise From Front Seat Frame

AFFECTED VEHICLE RANGE:

Range Rover (LG)

Model Year: 2013-2014

VIN: DA001204-EA127500

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A 'creak' noise from the base of the front seat may be evident.

Cause: This may be caused by insufficient lubricant during the assembly process.

Action: Should a customer express the concern, follow the Service Instruction outlined below

PARTS:



NOTE: To be sourced from the Squeaks & Rattles kit; refer to Technical Bulletin LTB00389NAS and Service Bulletin STE12-02 for more information and how to replenish the items in the Squeaks & Rattles Kit when necessary.

Nyogel 774L

Quantity: As necessary

TOOLS:

No Tools Required

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.



NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Apply Nyogel 774L grease to seat frame	05.10.10	0.1	42	LR041773



NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Adjust the affected front seat all the way forward.


2.  **NOTE: No parts need to be removed for access.**

Tilt the seat backrest all the way forward.

3.  **NOTE: Repeat this procedure on both sides of the seat frame.**

-  **NOTE: Apply Nyogel 774L grease to both sides of the seat frame in the areas shown.**

Apply Nyogel 774L grease from the Squeaks & Rattles Kit in the area shown.



4. Adjust the seat to the original position.