



Service Bulletin

File in Section: -

Bulletin No.: PI0538A

Date: February, 2013

PRELIMINARY INFORMATION

Subject: Tonneau Cover Contacts Rear Headrest when Lowering or Raising Convertible Roof

Models: 2012-2013 Corvette Convertible Models

This PI is being revised to add the 2013 model year. Please discard PI0538.

Condition/Concern

Some customers may comment that the tonneau cover will contact the rear headrests when the top is lowered or raised.

The new seats for 2012-2013 have a thicker headrest. When the seat is in the full back or tilted position, the headrest will come into contact with the top material when the top is lowered or raised.

Recommendation/Instructions

The dealership should move the seat forward to eliminate any contact with the roof before attempting any repairs. If the interference is not there with the seat forward, then no repairs should be attempted. The top and seats are operating as designed.