



Service Bulletin

File in Section: -

Bulletin No.: PI0883

Date: January, 2013

PRELIMINARY INFORMATION

Subject: HVAC Display Bezel Surface Discolored, Scratched or Deformed

Models: 2012-2013 Chevrolet Sonic
Equipped with HVAC RPOs C41, C60

Condition/Concern

Some customers may comment on the appearance of the HVAC display bezel surface being discolored, scratched or deformed.

Recommendation/Instructions

Replace the heater & A/C control bezel. **DO NOT** replace the heater and A/C control assembly for this condition. Replace **ONLY** the bezel, which is now serviced separately.

Remove the four screws that fasten the HVAC module to the bezel. Refer to Heater and Air Conditioning Control Replacement in SI.

Parts Information

Part Number	Description
95280632	Bezel, Heater & A/C Control
95280633	Bezel, Heater & A/C Control
95280634	Bezel, Heater & A/C Control

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
D9793*	Transferring HVAC Module to New Bezel	0.3 hr

*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.