



Service Bulletin

File in Section: -

Bulletin No.: PI0951

Date: July, 2013

PRELIMINARY INFORMATION

Subject: Body Plugs Visible on Vehicles Equipped with 6" Oval Accessory Chrome Assist Steps

Models: 2014 Chevrolet Silverado 1500 — White (RPOs GAZ, GBN) or Silver (RPO GAN)
2014 GMC Sierra 1500
Equipped with Chrome Assist Steps (RPOs VXH, BVQ)

Condition/Concern

Some customers may comment on the visibility with the body plugs on vehicles equipped with 6" oval accessory chrome assist steps.

This is due to the body plugs being black in color reflecting off of the chrome steps.

Recommendation/Instructions

Replace the black color body plugs with one of the plugs that pertains to the RPOs listed below.

		ORIGINAL EQUIPMENT	P/N 23157893	P/N 23137980
		BLACK	LIGHT GRAY	WHITE
GAZ	WHITE			X
GBA	BLACK	X		
GCN	VICTORY RED	X		
GXG	IRIDIUM MET.	X		
GWX	SUBTERRANEAN MET.	X		
G56	STEALTH GREY	X		
GAN	SWITCHBLADE SILVER		X	
GBN	WHITE DIAMOND			X
GTS	LUXO BLUE MET.	X		
GCE	SONOMA JEWELL MET.	X		

Parts Information

Part Number	Description	Qty
23157893	Plug, Rocker Outer Panel Hole (RPO GAN)	20
23137980	Plug, Rocker Outer Panel Hole (RPOs GAZ, GBN)	20

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1480008*	Body Plug Replacement	0.2 hr

*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.

Note: This transaction should be entered as a ZREG with the Customer Enthusiasm-Non Warranty Repair box checked.