



Service Bulletin

File in Section: -

Bulletin No.: PI1023A

Date: September, 2013

PRELIMINARY INFORMATION

Subject: Elimination of Rear Seat Floor Filler Trim Panel as Standard Equipment

Models: 2014 Chevrolet Equinox
2014 GMC Terrain

This PI has been revised to update the Condition/Concern information. Please discard PI1023.

Condition/Concern

Some customers may comment that their vehicle is missing the rear seat floor filler trim panel.



3559594

As shown in the graphic above, in previous model years 2010-2013, these vehicles included the rear seat floor filler trim panel as standard equipment.



3559595

Starting with 2014 vehicle production, the floor filler trim panel was eliminated as standard equipment. The seat/floor interface will now look like the example shown in the graphic above.

Recommendation/Instructions

No repairs are necessary and please advise the vehicle owner of the standard equipment change.

Note: The installation and cost of adding the floor filler panel will not be covered under the vehicle's warranty and would be at the customers expense.