



SERVICE BULLETIN

Notification of UPS3113-1b: Right-Hand C-Pillar Outer Panel Split on Leading Edge – Updated VIN List

05-JUN-13

No.: SGI13-12
(issue 2)

Section: GENERAL
INFORMATION

Market: CAN / USA

DESCRIPTION

A potential concern has been identified on a limited number of 2013 model year Land Rover LR2 vehicles where the leading edge of the outer panel on the right-hand C-pillar on the corner into the door shut area may be split.

AFFECTED VEHICLES

The VIN range of affected vehicles is DH356255-DH360221. Updated VIN / Retailer list on page 2.

ACTION TO BE TAKEN

Retailers are required to check DDW and **HOLD** all affected vehicles in the above VIN range that are in their control and refrain from releasing these vehicles for onward distribution, sale, or use pending completion of the inspection procedure detailed in Technical Bulletin UPS3113-1bNAS.

Thank you for your cooperation in this matter. Jaguar Land Rover apologizes for any inconvenience this may cause.

UPS3113-1b – AFFECTED VIN LIST

CANADA

VIN	RETAILER
DH358143	Budds' Imported Cars
DH357970	Land Rover Edmonton
DH358144	Land Rover Edmonton
DH359089	Land Rover Ottawa
DH358103	Land Rover Quebec City
DH358099	Land Rover Waterloo

USA

VIN	RETAILER	VIN	RETAILER
DH357733	Bob Moore Land Rover	DH357725	Land Rover Milford
DH357718	Land Rover Alexandria	DH357996	Land Rover North Point
DH357724	Land Rover Austin	DH358002	Land Rover North Point
DH358027	Land Rover Buckhead	DH357731	Land Rover Palm Beach
DH358050	Land Rover Buckhead	DH357426	Land Rover Paramus
DH358051	Land Rover Buckhead	DH357427	Land Rover Paramus
DH357419	Land Rover Cherry Hill	DH357428	Land Rover Paramus
DH357421	Land Rover Cherry Hill	DH357431	Land Rover Paramus
DH357370	Land Rover Fort Lauderdale	DH357432	Land Rover Paramus
DH357720	Land Rover Guilford	DH357434	Land Rover Paramus
DH357423	Land Rover Hanover	DH357435	Land Rover Paramus
DH357425	Land Rover Hanover	DH358003	Land Rover Shreveport
DH357710	Land Rover Hinsdale	DH357719	Land Rover Virginia Beach
DH358001	Land Rover Indianapolis	DH358012	Plaza Land Rover St. Louis