



# Service Bulletin

File in Section: -

Bulletin No.: PIC5781A

Date: November, 2013

## PRELIMINARY INFORMATION

**Subject:** Rotational Noise From The Rear Of The Vehicle When Braking

**Models:** 2012 - 2013 Chevrolet Sonic

**This PI was superseded to communicate repair information. Please discard PIC5781.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer may comment that there is rotational noise coming from the rear of the vehicle during brake apply. The noise might be found to be coming from the rear drum brake area.

### Recommendation/Instructions

To correct this concern, replace both Rear Brake Drums (P/N 95224012) and Brake Shoes on both sides of the vehicle (P/N 95145057). Parts are currently available in CCA inventory.

### Parts Information

Part Number	Description	Qty
95224012	Brake Drum	2
95145057	Shoe Kit	1

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2430220	Brake Shoe Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.