



# Service Bulletin

File in Section: -

Bulletin No.: PI1119

Date: November, 2013

## PRELIMINARY INFORMATION

**Subject:** Wrong Installation Instruction Sheets in Some Body Side Molding Accessory Kits

**Models:** 2012-2014 Chevrolet Cruze, Sonic

**Attention:** This PI applies to body side molding kit part numbers 95992461, 95980690, 95055169 and 95055168.

### Condition/Concern


Some technicians may comment that the instruction sheets included in the Cruze or Sonic Body Side Molding accessory kits are incorrect.

It has been found that the kit supplier may have inserted the wrong instruction sheets when packaging some of the accessory kits.


### Recommendation/Instructions

The accessory catalogue will be updated in the near future, however until that correction is available, technicians should follow the appropriate installation instructions noted below.

#### Cruze Instruction Sheets




① 95980690




3653569

②




③




3653570

④




⑤




3653571


⑥



⑦



3653572





3653573

Installation Instruction Sheet			Date	Revision
BODY SIDE MOLDING			1 - Jul - 11	Initial Release
Part No.	95175650	Sheet		



Sonic Instruction Sheets





03°C / 73°F




SERVICE




3




4



5



6



3653577



12h



48h



24h



KPH



MPH

3653573



Installation Instruction Sheet			Date	Revision
BODY SIDE MOLDING			13 - Jun - 12	Initial Release
Part No.	95954557	Sheet		