


L405 Radiator Date code.pptx

L405 Radiator Leak.JPG

Reference	SSM66477
Models	Range Rover (All New) / L405
Title	L405 Radiator Leak
Category	Engine
Last modified	21-Jun-2013 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p><b>Issue:</b> Loss of coolant, low level coolant warning displayed in the instrument cluster.</p> <p><b>Cause:</b> Supplier quality issue - Radiator is found to be leaking from the inlet (top) tank left hand end clench (see attached picture for reference)</p> <p><b>Action:</b> Replace radiator, part number LR034553. From the production dates of parts sent to Service (Neovia) the only affected radiators in <b>service stock</b> will have a date code of <b>12th Jan 2013</b> on the label (see attached example). If the radiator ordered from parts has a date code label other than 12th Jan 2013 it is ok to use. This SSM will be replaced with a Technical Bulletin at a later date.</p> <p><b>NOTE – Service stock was recalled and checked by the supplier, however if stock has been held at a Dealer it is recommended to check the date code prior to fitment.</b></p>




L25951 0P0A870AH43433ACD 12/01/13

**P5**

CALSONIC KANSEI UK

**CPLA 8005 AB**



**Coolant leak from radiator upper tank joints.**

