

No Graphics - Magna Camera (1)1.pdf

Reference	SSM68338
Models	LR2 / L359 Range Rover Evoque / L538
Title	Low Line Camera Display Missing Graphics
Category	Electrical
Last modified	20-Sep-2013 00:00:00
Symptom	205000 Electrical Accessories
Content	Title – Single Camera replaced due to graphical display failures Vehicles affected:- Range Rover Evoque -All Freelander 2/LR2 13MY Single Camera Option (Not Five Camera Surround System) Land Rover Freelander – Camera Option Issue :- Customers have reported that the graphical display on camera is missing Cause :- The causes are currently under investigation Action :- If investigating a customer complaint of no camera graphical display, then please follow the instructions described in the attachment